

# Technical Manual Index

## CT64-820-4 Turboprop

Component Maintenance Manual  
January 1, 2026

The manuals are listed in appendix number order.

The Rev. Cycle column indicates the following planned revision frequency for each publication listed:

AR - - - - - As Required revision cycle

| <u>Appendix Number</u> | <u>Publ. Number</u> | <u>Engine Model</u> | <u>Nomenclature</u>               | <u>Part Number</u>   | <u>VIN</u>   | <u>Manufacturer Name (Vendor Code)</u>                                   | <u>Basic Issue Date</u> | <u>Rev. No.</u> | <u>Rev. Date</u> | <u>Rev. Cycle</u> |
|------------------------|---------------------|---------------------|-----------------------------------|--|--|--|-------------------------|-----------------|------------------|-------------------|
| A1 & A2                | SEI-409             | CT64-820-4          | Fuel Control                      | 6028T87P01<br>6028T87P02<br>6028T87P04   | 757520-1<br>757520-2<br>757520-4                                   | Hamilton Sundstrand (73030)  | 5/30/76                 | 10              | 10/15/16         | AR                |
| A3                     | SEI-409             | CT64-820-4          | Lube & Scavenge Pump (Power Unit) | 5008T68P10   | GD-321-13  | Nichols Zenith Div, Parker Hannifin Corp. (86329)                        | 5/30/76                 | 10              | 10/15/16         | AR                |
| A4                     | SEI-409             | CT64-820-4          | Lube & Scavenge Pump (SDG)        | 5006T88P01<br>5006T88P03<br>5006T88P05<br>5006T88P06<br>5006T88P07<br>5006T88P08 | GM-555<br>GM-555-2<br>GM-555-4<br>GM-555-6<br>GM-555-7<br>GM-555-8 | Parker Hannifin Corp.<br>Parker Aerospace Fluid Systems Division (86329) | 5/30/76                 | 10              | 10/15/16         | AR                |
| A5 & A6                | SEI-409             | CT64-820-4          | Ignition Exciter                  | 4022T65P01   | 43661  | Unison Industries (59501)  | 5/30/76                 | 10              | 10/15/16         | AR                |
| A7 & A8                | SEI-409             | CT64-820-4          | Fuel Pump and Filter              | 5012T70P03   | 024836-117   | Hamilton Sundstrand (73030)  | 5/30/76                 | 10              | 10/15/16         | AR                |

# Technical Manual Index

## CT64-820-4 Turboprop

Component Maintenance Manual  
January 1, 2026

| Appendix Number | Publ. Number | Engine Model | Nomenclature               | Part Number                            | VIN        | Manufacturer Name (Vendor Code) | Basic Issue Date | Rev. No. | Rev. Date | Rev. Cycle |
|-----------------|--------------|--------------|----------------------------|--|------------|---------------------------------|------------------|----------|-----------|------------|
| A9              | SEI-409      | CT64-820-4   | Variable Geometry Actuator | 5006T68G04<br>5006T68G07<br>5006T68G09 |            | GE Aircraft Engines (99207)     | 5/30/76          | 10       | 10/15/16  | AR         |
| A10             | SEI-409      | CT64-820-4   | Flow Divider               | 5006T26G04                             |            | GE Aircraft Engines (99207)     | 5/30/76          | 10       | 10/15/16  | AR         |
| A11             | SEI-409      | CT64-820-4   | Anti-Icing Valve           | 4008T21P03<br>4008T21P05               | DC 10705-1 | GE Aircraft Engines (99207)     | 5/30/76          | 10       | 10/15/16  | AR         |
| A12             | SEI-409      | CT64-820-4   | Fuel Nozzle Assembly       | 4015T51P03                             | 25007      | Delavan Inc. (71895)            | 5/30/76          | 10       | 10/15/16  | AR         |

Questions or comments concerning the content of this index should be directed to [aviation.fleetsupport@ge.com](mailto:aviation.fleetsupport@ge.com).